Oil Field Environmental Incident Summary

Responsible Party: XTO ENERGY INC.

Well Operator: XTO ENERGY INC.

Well Name: TAT STATE FEDERAL 14X-36E

Field Name: BEAR CREEK Well File #: 30830

Date Incident:4/14/2016Time Incident:16:00Facility ID Number:County:DUNNTwp:148Rng:96Sec:36Qtr:

Location Description:

Submitted By: Kaylan Dirkx Received By:

Contact Person: Kaylan Dirkx

P.O Box 1589 Sidney, MT 59270

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building:

Distance Nearest Water Well:

Type of Incident: Equipment Failure

Release Contained in Dike: Yes - On Constructed Well Site Reported to NRC: No

Spilled Units Recovered Units Followup Units

Oil

Brine

Other 20 Barrels 20 Barrels 20 barrels

Description of Other Released Contaminant:

Kill mud

Inspected: Written Report Received: 6/17/2016 Clean Up Concluded: 4/14/2016

Risk Evaluation:

None, spill was contained and cleaned up immediately.

Areal Extent:

Potential Environmental Impacts:

Free fluids were recovered and returned to the tank, Impacted dirt was removed and put in the drill cutting mix (will be disposed to Chimney Butte Disposal).

Action Taken or Planned:

Cam lock was replaced with a hammer union and the tear in the liner was repaired.

Wastes Disposal Location: Free fluids returned to tanks and impacted soil was mixed with the drill cuttings which will be disposed at Chimney Butte Disposal.

Agencies Involved:

Updates

Date: 4/15/2016 Status: Reviewed - Assigned to Other Agency Author: Souder, Taylor

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

According to the report, the release remained on location. NDIC takes oversight.